

Ceiling Water Damage



Before: Toilet Leak from unit above



After: Leak fixed, ceiling repaired and repainted

Exterior Siding Repair



Before: Hole in the siding of home's chimney




After: Hole repaired and painted

Exterior Repairs



Before: If trees are too close to a house, they could begin to grow through your fence or cause cracks in the foundation



After: The trees were removed, as well as their stumps and a new section of the fence was installed.

Exterior Repairs



Before: Rotting soffit caused by overflow from clogged gutter



After: Soffit and gutter replaced